




# 3 Wire Mill Control With Lighted ON Run Switch with USP Start Protection 1 or 2 Stage Braking

Hitachi WJ200 VFD must be wired for source logic



**Momentary Switch**  
Use plunger or roller limit switch,  
When switch is engaged with back  
gear it switches the reverse input  
from R to F poles on the switch.